



Plug Replacement Instructions

FIG. 1.



FIG. 2.



FIG. 3.



- Step 1.** Cut cord and strip the wires as shown in **fig. 1.** then slide heat shrink over the cord.
- Step 2.** Connect wires as shown in **fig. 2.** Now spray lubricant on the plug so you can slide the heat shrink up over the plug.
- Step 3.** Now apply heat to the heat shrink until it looks like **fig. 3.**